

Thomas N. Miller



Garage Equipment and rolling road

The Algernon Road
Auction Rooms
Newcastle-upon-Tyne
NE6 2UN
United Kingdom

PLEASE NOTE END TIME EXTENDED AS INSTRUCTED BY
THE LIQUIDATOR

Ended 14 Aug 2022 19:26 BST

Lot	Description
1	An Automotech Electro-Hydraulic 2 Post Lift, model AS-6240TA, 4000 Kg. CONDITION REPORT: All lots are assumed to be working although sold strictly without guarantee. Please refer to Important sale information regarding the collection and removal of lots.
2	An Automotech Electro-Hydraulic 2 Post Lift, model AS-6246TAD-H, 4000 Kg. CONDITION REPORT: All lots are assumed to be working although sold strictly without guarantee. Please refer to Important sale information regarding the collection and removal of lots.
3	A Hunter Engineering Company Pro-Align 100 Series Wheel Aligner, with operating terminal, four wheel targets, sold together with an AutomechElectro-Hydraulic 4 Post Lift, model AS-6745, 4200Kg. CONDITION REPORT: All lots are assumed to be working although sold strictly without guarantee. Please ...[more]
4	An Automotech Electro-Hydraulic 2 Post Lift, model AS-6140A, 4000 Kg. CONDITION REPORT: All lots are assumed to be working although sold strictly without guarantee. Please refer to Important sale information regarding the collection and removal of lots.
5	A Dyno Developments 4WD Chasis Dynamometer (Rolling Road), sold with a Dyno Low-Noise Axial Fan, model SF94-2, control terminal, two heavy-duty ramps and the twin exhaust extraction unit with ducting. CONDITION REPORT: All lots are assumed to be working although sold strictly without guarantee. ...[more]
6	A Snap-On Sun Model STC 5325 Tyre Changer. CONDITION REPORT: All lots are assumed to be working although sold strictly without guarantee. Please refer to Important sale information regarding the collection and removal of lots.
7	A Snap-ON Sun model SWB 100 Wheel Balancer. CONDITION REPORT: All lots are assumed to be working although sold strictly without guarantee. Please refer to Important sale information regarding the collection and removal of lots.
8	A CTR Denso Thermal Systems Kheos Air Con Service Station. CONDITION REPORT: All lots are assumed to be working although sold strictly without guarantee. Please refer to Important sale information regarding the collection and removal of lots.
9	A CTR Denso Thermal Systems HFO-1234yf Air Con Service Station, sold together with three gas bottles. CONDITION REPORT: All lots are assumed to be working although sold strictly without guarantee. Please refer to Important sale information regarding the collection and removal of lots.
10	Approximately 58 car tyres, various sizes and manufacturers. (Q) CONDITION REPORT: Various sizes, various conditions and signs of use / damage. Please refer to Important sale information regarding the collection and removal of lots.